



Photo 1 – Northeastern edge of reservoir, facing northwest.



Photo 2 – Northern side of reservoir, facing north. One unnamed stream enters the reservoir from the north.



Photo 3 – Northern side of reservoir, facing northeast. A second unnamed stream enters the reservoir from the northeast.



Photo 4 – Eastern side of reservoir, facing northwest. This is the upper end of the reservoir.





Photo 5 – Eastern side of reservoir, facing west. This is the middle of the reservoir.



Photo 6 – Eastern side of reservoir, facing west. This is the lower end of the reservoir and the dam.



Photo 7 – Lower end of reservoir, dam and spillway, facing west.



Photo 8 – Spillway, facing west.





Photo 9 – Spillway and area below spillway, facing northwest.



Photo 10 – Unnamed stream channel approximately 50 feet below spillway, facing north.



Photo 11 – Unnamed stream channel approximately 100 feet below spillway, facing northwest.



Photo 12 – Unnamed stream channel approximately 150 feet below spillway, facing southwest.  
The fishing pond is visible in the background of this photograph.





Photo 13 – Fishing pond operated by the Willits KOA, facing northeast.



Photo 14 – Fishing pond operated by the Willits KOA, facing southwest.



Photo 15 – View of the dam from below, and PVC transfer line from the reservoir to the fishing pond facing northwest.